US ERA ARCHIVE DOCUMENT

UNIT LOG		Incident Name Kalamazoo River/Enbridge Oil Spill			e Prepared 2/2012	3. Time Prepared 1700	
			Unit Leader (Name and Position) Ielinda Leutke, Planning Section Chief			6. Operational Period 0700, 03/08/2012 – 0700, 03/15/2012	
7.		1	Personnel Roster Assig	ned		,	
	Name		ICS Position			Contact Phone	
Larry Rader			Situation Unit				
8. Time -	I		Activity Log	- F			
7ime 0900	Major Events Observations:						
	 Talmadge Creek, observed sweeper boom installed in culvert on east side of 15-1/2 Mile Road. 						
		Talmadge Creek, observed restoration along creek west of 15-1/2 Mile Road.					
		 Observed crews continuing mat removal at former Turbidity Control Structure location. 					
		 Observed stacked mats at former Turbidity Control Structure location. 					
	• Ol	stem piping onto	0				
	• Ta	Talmadge Creek: observed restoration work near MP1.5.					
		Mat road removal continued south of A Drive, upstream from Confluence.					
		Talmadge Creek: observed crews loading mats onto truck on A Drive at Confluence.					
	• Co	Confluence, restoration work appeared almost complete.					
		Confluence, observed crews excavating former soil mixing box location.					
		Observed crews conducting water quality monitoring just upstream from Confluence.					
		Confluence: observed containment boom and safety equipment just downstream from Talmadge Creek discharge.					
	• Co	onfluence:	containment boom in p	lace at Ta	almadge Creek	discharge.	
	• Co	onfluence:	minor debris observed	within cor	ntainment boom	ı.	
	• Co	onfluence:	observed restoration w	ork along	river shoreline.		
	• Fr	ac Tank C	ity Cell A, only two sma	all piles of	soil present in o	cell.	
	• Fr	ac Tank C	ity Cell B, no material c	r activity o	observed.		
		ac Tank C Il-off box.	ity southern decon pad	, crews cle	eaning a frac ta	nk and	
1500	Return to ICF)					
1500 Return to ICP. 9. Prepared by (Name and Position)							
			eader, USEPA-START				